Security information

	AIR	A STATE OF THE STA	25X1 25X1
s utta		14 December 1953	25X1
	REF:		

- 1. The non-compatibility of equipment created by the use of a new type of interconnecting plug in the RS-6 has created a serious problem for . A number of projects supported by this area are utilizing both RS-1 and RS-6 sets which means that the CH-58 can be fitted with a plug to connect with either, but not both sets.
- 2. The current practice of issuing a new plug in the RS-6 spare parts kit to replace the normal CN-58 plug is not a satisfactory solution since the field operators must be able to use the CN-58 with either set. While changing the plug is a relatively simple operation, it is not one we wish to leave to the staybehind operator faced with difficult conditions and a minimum of experience.
- 3. Paragraph 2.b of the reference states that all GN-58 cords were to be converted to the new plugs, presumably during the early part of 1953. Since we have not been advised as to whether the plug conversion was accomplished, we are somewhat concerned as to which plugs are currently being supplied with GN-58. Specifically, the final shipment of GN-58's was recently

supplied and also the status of the proposed conversion of all GN-50 plugs as montioned above.

4. As to the overall solution to this non-compatibility problem, Para.

2.c of the reference advised that adaptor plugs were to be obtained which would adapt the old GN-56 plug to the new RS-6 plugs. This would then allow the GN-56 to be used with either the RS-1 or the RS-6. This obviously is the only real solution to our problem. To date we have received no further word on these adaptors and they are becoming an urgent requirement for our operations. Therefore we request the following action:

SECURITY INFORMATION

25X1

25X1

SECRET SEJRITY INFORMATION

A. If the CI-50 plugs have not been replaced with the new plug, an adapter be presured as soon as possible which would adapt the old plug to the RS-6 requirement.

- B. If the CH-58 plugs have been converted, an adaptor be presured to allow the RS-1/M-2 operation with the RS- CH-58 plugs.
- 5. Your early attention to this matter and advice on the problem will be greatly appreciated.

Motribution: NUMB : 3

> SECULTI SECURITY INFORMATION

Cherry Services 1971

25X1